

REPORT ON BOUNDARY MAINTENANCE OR

FIELD NOTES OF RESTORATION OR

REPLACEMENT OF A MONUMENT

50916, 51720, 51811, 56216,
SHOWN ON C.L.S.R. PLAN 65762, 65763, 65764, 68136

CANADA LANDS SURVEYS RECORDS

F.B. 30403 - 246

Sheet .1 of 2

DATE: 4 MARCH 1987.

Type of survey work boundary maintenance Date work done December, 1986

Indian Reserve or other Lands Fisher's Grant I.R. no. 24, 24G, & Boat Harbour I.R. no. 37
5202-F1-24, 5202-F1-24G.

Province or Territory Nova Scotia File 5202-B2

REPORT OR SKETCH (See over)

This survey was carried out by myself and a helper. Monuments were located by rough measurements. All lines were cut out using band labourers.

Fisher's Grant I.R. no. 24

C.L.S. standard post IR 4 was not found but found pits and mound. Caps were missing on C.L.S. standard posts IR 3, IR 6, and IR 10.

Lines IR3- IR4-IR 6 and IR 9- IR8- IR7 had previously been cut very wide and a number of the blazes found were more than 3' from the line. There was fewer than normal trees close enough to the line to be suitable for blazing.

All lines were well defined and found with varying degrees of growth.

Wood reference posts were replaced at IR 2, IR4, IR 5, IR8, and IR9. Posts found at other locations were sound. All lines were blazed and painted. A C.L.S. 69 post was found near IR7 and a wood reference post was placed beside it.

Fisher's Grant I.R. no 24G

All lines were well defined and found with varying degrees of growth

Line IR 5- IR 6 could not be reached because of flooding between the line and the main part of the property. A wood post could be seen at IR 5 at the edge of the water.

Wood reference posts were replaced at IR 1, IR 2, IR 3, and IR 4. All lines were blazed and painted.

Boat Harbour I.R. no. 37

All lines were well defined and found with varying degrees of growth.

C.L.S. standard post IR 7 was not found but found 2" by 4" wood reference post.

Lines along the centre of the old Glenfalloch Road required very little cutting and had few trees suitable for blazing.

Wood reference posts were replaced at IR 1, IR 2, IR 14, IR 13, IR 12, IR 11,

Certified Correct

(Signature, Commission as Surveyor)

(Place)

(Date)

John C. Sutherland N.S.L.S.

New Glasgow, N.S.

Jan. 23, 1987

Robert 87-02-13

FB 30403

REPORT ON BOUNDARY MAINTENANCE OR

FIELD NOTES OF RESTORATION OR

REPLACEMENT OF A MONUMENT

SHOWN ON C.L.S.R. PLAN 50916, 51720, 51811, 56216,
65762, 65763, 65764, 68136

CANADA LANDS SURVEYS RECORDS

F.B. 30403 - 246

Sheet 2. of 2

DATE: 4 MARCH 1987.

Type of survey work . boundary maintenance Date work done December, 1986

Indian Reserve or other Lands . Fishers Grant I.R. no. 24, 24G, & Boat Harbour I.R. no. 37
5202-F1-24, 5202-F1-24G,

Province or Territory . Nova Scotia File 5202-B2

REPORT OR SKETCH (See over)

IR 10, IR 9, IR 7, IR 26, IR 60, and IR 63. Posts found at other locations were sound. All lines were blazed and painted.

Certified Correct

(Signature, Commission as Surveyor)

John C. Sutherland N.S.L.S.

(Place)

New Glasgow, N.S.

(Date)

Jan. 23, 1987

Covert 87-02-13

FD 30403